






	Tvar	Obj. číslo	DxTxH	PxF	Specifikace	Poznámka	
	1	666529	400x60x127		89A 802 J8A V217	Pro jemnější jakost povrchu	
		666530	400x40x127		89A 802 J8A V217		
		666532	400x50x127		89A 802 J8A V217		
	1	441403	200x20x51		F13A 46 HH11 V	Pro hrubovací operace	
		441401	225x25x51		F13A 46 HH11 V		
		441399	250x25x51		F13A 46 HH11 V		
		469827	250x25x76,2		F13A 46 HH11 V		
		365997	300x30x76,2		F13A 46 HH11 V		
		665267	300x50x76,2		F13A 46 HH11 V		
		665269	300x50x127		F13A 46 HH11 V		
		665282	350x40x127		F13A 46 HH11 V		
		665294	350x50x127		F13A 46 HH11 V		
		665295	400x40x127		F13A 46 HH11 V		
	1	664563	225x25x51		93A 46 H8A V217		
		664566	250x25x76,2		93A 46 H8A V217		
		498402	250x25x51		93A 46 H8A V217		
		849597	300x30x76,2		93A 46 H8A V217		
		524016	350x40x127		93A 46 H8A V217		
		357751	355x50x127		93A 46 H8A V217		
		793338	400x60x127		93A 46 H8A V217		
		117241	400x50x127		93A 46 H8A V217		
			5	260141	300x50x76,2		155x10
467466	350x50x127			200x10	89A 46 I8A V217		
548613	400x50x127			200x10	89A 46 I8A V217		
664574	300x50x127			190x10	89A 46 I8A V217		
664584	300x50x76,2			155x10	89A 802 J8A V217		
664626	300x50x127			190x10	89A 802 J8A V217	Pro jemnější jakost povrchu	
664632	400x60x127			200x10	89A 802 J8A V217		
	5	664478	300x50x76,2	155x10	F13A 46 HH11 V	Pro hrubovací operace	
		593712	400x50x127	200x10	F13A 46 HH11 V		
		665297	350x50x127	200x10	F13A 46 HH11 V		