





Thread Repair Kits

for oxygen sensor thread M 18x1,5
HexTap LS and LSN
Wire Inserts LS Inconel X750 (19149),
Solid Inserts LS (19147)

Kit Ripristina Filetti

per filetti sonda Lambda M 18x1,5
HexTap LS e LSN
Filetti Riportati LS Inconel X750 (19149)
inserti filetti LS (19147)



	 LSN	 LS	 19147	 19149	Art.-No.	€
10E	M 18 x 1.5	M 20 x 1.5		10	19102	75,00
5EB	M 18 x 1.5	M 20 x 1.5	5	5	19104	80,00
10B	M 18 x 1.5	M 20 x 1.5	10		19106	85,00

